



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

October 28, 2003

TO: Minerals File

FROM: Tom Munson, Senior Reclamation *TM*

SUBJECT: Site Inspection, Rocanville Stone Company, Tejon 1,2,3, (E/027/069), Red Gulch Quarry and Levin #2 Mine (S/027/087), Millard County, Utah

Date of Inspection: September 17, 2003
Time of Inspection: 10:00 a.m. - 1 p.m.
Conditions: Sunny
Participants: Mert Hamilton, Rocanville Stone; Larry Garahana and Sherri Wysong, BLM; Tom Munson, DOGM

Purpose of Inspection: To determine the amount of disturbance at all the mine and exploration site locations based on the Division's Neighboring and Related Sites Policy.

Getting to the site: The project areas are located on the road traveling up North Canyon in the Southern part of the House Range (T13W, R18 S)

Observations:

The Division and BLM met Mr. Mert Hamilton at the Levin #2 mine site location. Also inspected was the Red Gulch Quarry area which was recently transferred from Larry Dutson to Mert Hamilton and the newly permitted Tejon 1, 2, 3 exploration sites.

When the Red Gulch Quarry site was transferred, The Division's Neighboring and Related Sites Policy was applied and that project was combined with the Levin Stone #2 site under file S/027/087. Larry Dutson's Red Gulch file #S/027/098 was closed at that time.

During this inspection, all the sites were GPS'd by Larry Garahana and Tom Munson (map attached). It was determined that the disturbance at the Levin #2 site was 4.67 acres, the Red Gulch Quarry 2.93 acres, the Tejon 1 site 1.32 acres and the Tejon 2 site .99 acres, bringing the total of all areas to 9.91 acres of disturbance. Nothing had been done at the Tejon #3 site at the date of this inspection.

Rocanville Stone - Levin#2

Page 2 of 2

S/027/087

Inspection Date:9/17/2003; Report Date: 10/28/2003

There was a crew splitting the rock that was being commercially mined at all the above mentioned sites. The inspection was terminated around 1 p.m.


Conclusions and Recommendations:



It is recommended that the Division ask Mr. Hamilton to immediately post a transitional reclamation surety bond to cover the 9.91 acres of existing disturbance, and within 60 days submit a Notice of Intention to Conduct Large Mining Operations to cover the existing disturbance and any proposed expansion. We should also require Mr. Hamilton to mark the 9.91 acres of existing disturbance and notify him that he may not expand beyond that area until the LMO is approved and adequately bonded.

TM:jb

cc' Larry Garahana, BLM, Fillmore FO
Mert Hamilton, Rocanville Stone

O:\M027-Millard\S0270087 Levin Stone#2\inspections\insp-09172003.doc



 <p>Dept. of Natural Resources Division of Oil, Gas & Mining Mineral Mines Program</p>	<p>500 0 500 Feet</p> <p>Scale 1:8000 Contour Interval 40 feet</p>	<p>N</p> 	<p>Mine Number: S027/087 & E027/069 Mine Name: Levin Stone #2 Township 18 S Range 13 West Section 29 & 30</p>		
<p>Quad Sheet: Miller Cove Quadrangle Q2508</p>			<p>Drafted by TM</p>	<p>September 2003</p>	<p>Operator: Rocanville Stone</p>